

GET THIS **LOOK**



GET THIS LOOK

SKILL LEVEL:
INTERMEDIATE



Equipment



- Vinyl Cutter
- Heat Press

Garment



J. America — Melange Fleece Colorblocked Hooded Pullover (#8676)

Materials



- CAD-CUT® Adhesive
- Silver Heat Transfer Foil
- CAD-CUT® Flock Black

Accessories



- 11" x 15" Hotronix® Quick Change Platen
- 16" x 20" Hotronix® Quick Change Platen
- Cover Sheet

How-To Instructions



Temperature: 320 degrees

Pressure: Various, noted

1. Load garment on 11" x 15" platen (landscape)
2. Preheat garment to release any moisture & wrinkles
3. Place CAD-CUT® Flock, place cover sheet, tack for 2 seconds with medium pressure
4. Peel cold
5. Place CAD-CUT® Adhesive, place cover sheet, apply for 5 seconds with light pressure
6. Peel hot
7. Cover CAD-CUT® Adhesive with Silver Heat Transfer Foil, place cover sheet, apply for 8–10 seconds with firm pressure
8. Peel cold
9. Unload the 11" x 15" platen and replace with the 16" x 20" platen
10. Load the back of hoodie on the platen, preheat to release moisture and wrinkles
11. Repeat application steps above for the design on the back