

GET THIS **LOOK**



GET THIS LOOK

SKILL LEVEL:
INTERMEDIATE



Equipment



- Vinyl Cutter
- Heat Press

Garment



Boxercraft — Black & Gold Flannel Pant, Style F20BG-2; Socks locally purchased

Materials



- CAD-CUT® Flock II – White, Black, Yellow

Accessories



- Sleeve/Leg Platen
- 16"x20" Heat Printing Pillow
- Thermo-Tape™
- EZ Weeder®
- Kraft Paper Cover Sheet

How-To Instructions



Temperature: 330° degrees

Pressure: Medium

1. Cut CAD-CUT® Flock II on vinyl cutter – Be sure to MIRROR DESIGN.
2. Weed designs.
3. Pull pants pocket inside-out to create smooth heat printing area.
4. With the Sleeve/Leg Platen loaded on press, thread pants.
5. Preheat to remove moisture and wrinkles from garment.
6. Place design.
7. Press for 18 seconds using a cover sheet.
8. CAD-CUT® Flock II is a cold peel; set pants aside to peel later.
9. Remove Sleeve/Leg Platen, load 16"x20" Platen onto press with heat printing pillow.
10. Place socks, bottom side up, on the heat printing pillow.
11. Preheat to remove moisture and wrinkles.
12. Place designs using Thermo-Tape™ to keep socks from moving while being pressed.
13. Press for 18 seconds using a cover sheet.
14. CAD-CUT® Flock II is a cold peel; set pants aside to peel later.
15. Peel cold.