

GET THIS
LOOK



GET THIS LOOK

SKILL LEVEL:
INTERMEDIATE



Equipment



- Vinyl Cutter
- Heat Press

Garment



SanMar — OGIO Endurance, Style LOE501

Materials



- CAD-CUT® Hi-Vis Color Reflect Heat Transfer Vinyl, Pink

Accessories



- 6"x10" Interchangeable Platen
- Print Perfect Pads
- Kraft Paper Cover Sheet
- EZ Weeder®

How-To Instructions



Temperature: 325° - 350° degrees

Pressure: Medium

1. Cut CAD-CUT® Hi-Vis Color Reflect HTV on vinyl cutter.
2. Weed design.
3. Insert Print Perfect Pad into sleeve.
4. Place sleeve design on 6"x10" Interchangeable Platen.
5. Press at 325° - 350° degrees for 20 seconds at medium pressure using a cover sheet.
6. Remove Print Perfect Pad.
7. Rotate platen to portrait mode.
8. Load garment to print on left chest.
9. Preheat garment to remove moisture and wrinkles.
10. Place design.
11. Press at 325° - 350° degrees for 20 seconds at medium pressure using a cover sheet.
12. Load garment to print on hood.
13. Preheat garment to remove moisture and wrinkles.
14. Fold design and pinch to find center to help center design placement.
15. Place design.
16. Press at 325° - 350° degrees for 20 seconds at medium pressure using a cover sheet.
17. Realign garment and press remaining design along hood.
18. Peel all designs cold.

