

GET THIS
LOOK



GET THIS LOOK

SKILL LEVEL:
BEGINNER



Equipment



- Vinyl Cutter
- Heat Press

Garment



SanMar® — Port Authority® Enhanced Visibility Vest, Style SV01

Materials



- CAD-CUT® Hi-Vis Color Reflect - Black

Accessories



- 11"x15" Interchangeable Platen
- Kraft Paper Cover Sheet
- EZ Weeder®

How-To Instructions



Temperature: 325° degrees

Pressure: Medium

1. Cut CAD-CUT® Hi-Vis Color Reflect on vinyl cutter.
2. Weed design.
3. Load vest on 11"x15" platen.
4. Preheat to remove moisture and wrinkles from vest.
5. Slide vest over and preheat remaining portion.
6. Place design.
7. Align vest so zipper and seams hang off the platen.
8. Press for 20 seconds using a cover sheet.
9. Slide vest over and press remaining portion.
10. Press for 20 seconds using a cover sheet.
11. CAD-CUT® Hi-Vis Color Reflect is a cold peel; peel carrier after final application.
12. Remove vest then rotate platen to portrait mode.
13. Reload vest on platen for back application.
14. Preheat to remove moisture and wrinkles from vest.
15. Place design.
16. Press for 20 seconds using a cover sheet.
17. Peel cold.