

GET THIS
LOOK



GET THIS LOOK

SKILL LEVEL:
ADVANCED



Equipment



- Vinyl Cutter
- Print/Cut System
- Heat Press

Garment



J. America — Women's Glitter French Terry
Hooded Pullover, Style 8860

Materials



- CAD-CUT® Glitter Flake™ - Red
- CAD-COLOR® Express Print®
- Magic Mask® Medium Tack

Accessories



- 11"x15" Interchangeable Platen
- EZ Weeder®
- Squeegee
- Kraft Paper Cover Sheet

How-To Instructions



Temperature: 300°F degrees

Pressure: Medium

1. Cut CAD-CUT® Glitter Flake™ on the vinyl cutter.
2. Print and cut CAD-COLOR® Express Print® on solvent or eco-solvent printer.
3. Weed designs.
4. Apply Magic Mask® to Express Print®.
5. Squeegee from center out to remove air bubbles.
6. Peel Express Print® carrier off the design.
7. Load garment onto heat press.
8. Preheat to remove moisture and wrinkles from garment.
9. Place Express Print®.
10. Tack for 5 seconds using a cover sheet.
11. Peel warm.
12. Place CAD-CUT® Glitter Flake™.
13. Tack for 5 seconds using a cover sheet.
14. Peel hot.
15. Press for 15 seconds using a cover sheet.