

GET THIS
LOOK



GET THIS LOOK

SKILL LEVEL:
INTERMEDIATE



Equipment



- Vinyl Cutter
- Heat Press

Garment



QuikFlip™ Apparel — Charcoal Hero Hoodie Pullover

Materials



- CAD-CUT® Reflective II

Accessories



- 11"x15" Interchangeable Platen
- 6"x10" Interchangeable Platen
- EZ Weeder®
- Kraft Paper Cover Sheet

How-To Instructions



Temperature: 290°F degrees
Pressure: Medium

1. Cut CAD-CUT® Reflective II on the vinyl cutter.
2. Weed design.
3. Load garment onto heat press with 11"x15" platen in place.
4. Preheat to remove moisture and wrinkles from garment.
5. Place design on front of jersey, press for 10-12 seconds using a cover sheet.
6. Peel hot.
7. Load 6"x8" platen onto heat press.
8. Load sleeve onto heat press.
9. Preheat to remove moisture and wrinkles.
10. Place design then press for 10-12 seconds using a cover sheet.
11. Peel hot.
12. Flip hoodie into backpack.
13. Load backpack onto heat press.
14. Preheat to remove moisture and wrinkles.
15. Place design then press for 10-12 seconds using a cover sheet.
16. Peel hot.